



These transistors and resistors
 01R75001 to be one part each.
 If not available, may be
 possible to replace with
 24B7098RL, but not sure.